



Westin Maui Resort & Spa

Customer since 2015 uses the Clamp-on
unit in kitchen and laundry

The Westin Maui Resort & Spa installed a Vodaa water treatment device on our 3" hot water line feeding the Laundry facility on property. Once the Vodaa system was installed we started noticing large amounts of scale mixed with lint coming out of the machine... We know for certain that the Vodaa system was responsible for removing the scale, because the water softener was not operational. Since the first initial installation at our laundry, we have added two more treatment units to our hot and cold water supply lines to our main kitchen. Again we started seeing almost instant results. I am truly amazed at the difference.

Prior to the installation of the treatment system, the unit was completely packed with hard water deposits all around the walls and the exchanger tubes. The deposits were very hard and would require a hammer and chisel to remove them. Now the system is almost completely free of hard water deposits and what is still in there is soft and can be easily removed. We have also seen positive results with our glass washer. The glasses are cleaner than ever and require less detergent. In all, by removing scale throughout our facility we are saving money on labor, consumables, water and energy.

Sincerely,

The Chief Engineer
The Westin Maui Resort & Spa