



Sheraton Maui Resort & Spa

Customer since 2017
Drop-in Technology on swimming pool

The new water treatment equipment that your company has supplied to the Hotel has generated some surprisingly good, preliminary numbers. Our swimming pools chlorine generator's run time has decreased from 24 hours per day, down to 16 hours. The chlorinator was previously not able to keep up with the demand, therefore chlorine granules were also having to be added to maintain the proper level of chlorine, and now we are no longer adding granules. We have also seen a reduction in the use of salt by the chlorinator by almost 50%, and the water in the swimming pools appear to be clearer. Although these are just some preliminary numbers, I feel confident that this device is going to continue to generate savings. I will continue to update you as we get more data from the process.

Sincerely,
Director of Engineering